

## Pipe penetration cold roof self-adhered

1. Primer FG35.
2. Resitrix SK membrane self-adhered onto primed substrate.
3. Hot air weld.
4. Resitrix SKW membrane stretched over the pipe penetration and hot-air welded to field membrane.
5. Resitrix SKW membrane stretched over the pipe penetration and hot-air welded to field membrane.
6. Jubilee clip.

