

## Pipe penetration warm roof self-adhered

1. Recommended insulation installed as per the manufacturer's recommendations.
2. Primer FG35.
3. Resitrix SK membrane self-adhered onto primed substrate.
4. Hot air weld.
5. Resitrix SK membrane stretched over the pipe penetration and hot-air welded to field membrane.
6. Alutrix Vapour Barrier self-adhered onto primed substrate. Not required when using existing roof as vapour barrier.
7. Resitrix SK membrane stretched over the pipe penetration and hot-air welded to field membrane.
8. Jubilee clip.

