

Drop outlet cold roof

1. Resitrix Drop Outlet .
2. RESITRIX SKW membrane factory attached to Drop Outlet and hot air welded onto field membrane.
3. Hot air weld
4. RESITRIX SKW membrane self-adhered onto primed substrate.
5. Primer FG35.
6. Roof deck.
7. Suitable insulation installed to avoid thermal bridging.

