

Metal coping warm roof self adhered

1. Coping system installed as per manufacturer's specifications.
2. RESITRIX SKW membrane self-adhered onto primed substrate and hot air welded onto field membrane.
3. Primer FG35.
4. Hot air weld.
5. RESITRIX SKW membrane self-adhered onto primed insulation.
6. ALUTRIX 600 Vapour Barrier self-adhered onto primed substrate. Not required when using existing roof as vapour barrier.
7. Recommended insulation installed as per the manufacturer's recommendations.

