

## Stone coping termination

1. Primer with FG35.
2. RESITRIX SKW membrane self-adhered onto primed substrate and hot air welded onto field membrane.
3. Mortar bed.
4. Stone coping embedded in mortar.

